

03500.014272.



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

HIDESHI KAWASAKI

Appl. No.: 09/512,360

Filed: February 24, 2000

For: METHOD FOR PRODUCING  
ELECTRON SOURCE, ELECTRON  
SOURCE PRODUCED THEREBY,  
METHOD FOR PRODUCING IMAGE  
FORMING APPARATUS AND IMAGE  
FORMING APPARATUS PRODUCED  
THEREBY

U.S. Patent No.: US 6,878,027 B1

Issued: April 12, 2005

Examiner: Mariceli Santiago

Art Unit: 2879

July 24, 2006

**Certificate**  
**JUL 28 2006**  
**of Correction**

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**CERTIFICATE OF CORRECTION**  
**UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

07/27/2006 HALI11 00000028 6878027

01 FC:1811

100.00 UP

**AUG 01 2006**

Accompanying this letter is a check for \$100.00 to cover the statutory fee  
for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our New York office  
by telephone at (212) 218-2100. All correspondence should continue to be directed to our  
address given below.

Respectfully submitted,



---

Frank A. DeLucia  
Attorney for Patentee  
Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
Facsimile: (212) 218-2200  
NY\_MAIN 518472v1

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,878,027 B1

DATED : April 12, 2005

INVENTOR(S) : HIDESHI KAWASAKI

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE [56] REFERENCES CITED

Foreign Patent Documents, "JP 0 660 357 A1 6/1995" should read  
--EP 0 660 357 A1 6/1995--.

COLUMN 9

Line 52, "manner," should read --manners,--.

COLUMN 13

Line 63, " $T_{SCAN}$ ," should read -- $T_{scan}$ --.

COLUMN 19

Line 56, " $D_{y(a-2)bc+1}$ " should read -- $D_{y(a-1)bc+1}$ --.

COLUMN 21

Line 8, " $1 \times 10^{-4}$ " should read -- $1 \times 10^{-4}$ --; and  
Line 27, "In" should read --Ie--.

COLUMN 23

Line 65, "No. 10 11," should read --No. 10 111,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,878,027 B1

No. of add'l. copies  
@ 30¢ per page



Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,878,027 B1

DATED : April 12, 2005

INVENTOR(S) : HIDESHI KAWASAKI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24

Line 11, "11\*." should read --11%.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,878,027 B1

No. of add'l. copies  
@ 30¢ per page



AUG 01 2006

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,878,027 B1

DATED : April 12, 2005

INVENTOR(S) : HIDESHI KAWASAKI

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE [56] REFERENCES CITED

Foreign Patent Documents, "JP 0 660 357 A1 6/1995" should read  
--EP 0 660 357 A1 6/1995--.

COLUMN 9

Line 52, "manner," should read --manners,--.

COLUMN 13

Line 63, "T<sub>SCAN</sub>," should read --T<sub>scan</sub>--.

COLUMN 19

Line 56, "D<sub>y(a-2)bc+1</sub>" should read --D<sub>y(a-1)bc+1</sub>--.

COLUMN 21

Line 8, "1x10<sup>-4</sup>" should read --1x10<sup>-4</sup>--; and  
Line 27, "In" should read --Ie--.

COLUMN 23

Line 65, "No. 10 11," should read --No. 10 111,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,878,027 B1

No. of add'l. copies  
@ 30¢ per page



Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : US 6,878,027 B1

DATED : April 12, 2005

INVENTOR(S) : HIDESHI KAWASAKI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24

Line 11, "11\*." should read --11%.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,878,027 B1

No. of add'l. copies  
@ 30¢ per page



AUG 01 2006